



## Contents

<b>Firmware V1.08 2022-12-08</b> .....	2
<b>Firmware V1.07 2022-03-28</b> .....	2
<b>Firmware V1.06 2020-08-16</b> .....	2
<b>Firmware V1.04 2020-10-30</b> .....	2
<b>Firmware V1.03 2020-09-03</b> .....	2
<b>Firmware V1.02 2019-03-28</b> .....	3



## GV-IP Decoder Box Plus Version History

### Firmware V1.08 2022-12-08

**Fixed:**

- Live view error when operating via GV-IR Remote Control

### Firmware V1.07 2022-03-28

**Fixed:**

- Issue of frequent disconnection to GV-EBD4813 when Smart functions are enabled on the camera
- Issue of live view lagging when connecting to UA-R800F2
- Failure of connecting to UA-R500F2

### Firmware V1.06 2020-08-16

**Fixed:**

- Audio malfunction for the IP cameras newly added

### Firmware V1.04 2020-10-30

**New:**

- Support for Stream Mode function, providing the selection of single stream and dual stream
- Support for applying a stream mode and loop time interval to all newly-added IP devices

**Fixed:**

- Chances of failure to display resolutions of 2595 x 1944 and 2688 x 1520 in single view

### Firmware V1.03 2020-09-03

**Fixed:**

- Chances of disconnection or image error when streaming live views in loop mode



- Chances of audio malfunction on directly connected GV-FER12700
- Chances of failure to save password changes using GV-IP Device Utility V8.9.0 or earlier

### **Firmware V1.02 2019-03-28**

**Fixed:**

- Inability to operate / access certain functions when using a wireless mouse
- Disconnecting of live view images, for 5 ~ 10 minutes, after system reboot
- Screen flashing upon adding of IP devices
- Ability to configure unauthorized, grayed-out settings under Lock Operation even when it wasn't enabled
- Exiting the PTZ controls of a PTZ device after 30 ~ 60 seconds of idling when using GV-Joystick V2