



Contents

Firmware V2.50 2022-04-18	2
Firmware V2.41 2021-09-08	3
Firmware V2.40 2021-06-07	3
Firmware V2.32 2021-01-26	4
Firmware V2.31 2020-07-02	4
Firmware V2.21 2019-08-17	5
Firmware V2.20 2019-05-13	6
Firmware V2.15 2018-08-14	6
Firmware V2.12 2018-01-16	7
Firmware V2.11 2017-11-09	7
Firmware V2.00 2017-08-15	8
Firmware V1.41 2016-12-09	9
Firmware V1.40 2016-03-10	9
Firmware V1.30 2015-04-09	10
Firmware V1.23 2014-11-11	11
Firmware V1.22 2014-04-14	12
Firmware V1.20 2013-12-09	13
Firmware V1.10 2013-05-28	13



GV-AS21xx, GV-AS41xx and GV-AS81xx Version History

Firmware V2.50 2022-04-18

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

IMPORTANT: Users must read the necessary [upgrade instructions](#) carefully before upgrading GV-AS21 / 41 / 81 Series Controller to firmware V2.31 or later.

New:

- Support for Visitor mobile cards (only compatible with GV-QR1352 firmware V1.10 and GV-Mobile Access app V1.10, or later versions)

Fixed:

- Failure to open the Web interface using Microsoft Edge and Google Chrome on Windows 11 and 10
- Chances of failure to detect the controller using GV-IP Device Utility
- Failure to exit a monitored area set up with the Area Occupancy function and GV-ASManager V6.0 (only for GV-AS810 / 8110 / 8111)

Modified:

- SSL certificate updated



Firmware V2.41 2021-09-08

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

IMPORTANT: Users must read the necessary [upgrade instructions](#) carefully before upgrading GV-AS21 / 41 / 81 Series Controller to firmware V2.31 or later.

New:

- Support for GV-RKD1352 card reader via Wiegand

Firmware V2.40 2021-06-07

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111

New:

- Support for GV-DES1352 / GV-QR1352 (for the features of dynamic QR codes and smart phone access, it is required to work with GV-ASManager V5.3.3)
- Issue of time disparity after disconnected from GV-ASManager for a certain period of time



Firmware V2.32 2021-01-26

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

IMPORTANT: Users must read the necessary [upgrade instructions](#) carefully before upgrading GV-AS21 / 41 / 81 Series Controller to firmware V2.31 or later.

Modified:

- Interlock function by which an interlocking door is closed when its associated door unlocks, in addition to being open

Firmware V2.31 2020-07-02

version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

IMPORTANT: Users must read the necessary [upgrade instructions](#) carefully before upgrading GV-AS21 / 41 / 81 Series Controller to firmware V2.31 or later.

New:

- Support for software licensing for GV-ASManager V5.3.0 or later

Fixed:

- Cybersecurity enhanced as follows:
 - Removing user account for engineering mode
 - Fixing misuse of the same cryptographic key to prevent MITM attacks
 - Requiring certain levels of authentication for system log disclosure
 - Buffer overflow vulnerability addressed, with enhanced security protecting devices from plausible unauthenticated cyberattacks
- Incorrectly reflecting DST (Daylight Saving Time) end date and time on Web interface



- Chances of inability to store snapshots, into the SD card, captured from extended readers
- Inability to connect GV-AI FR to controllers by IP connection on GV-ASManager, and requiring additional configuration via the controllers' Web interface

Improved:

- Reestablishing port connection periodically in inhibiting unauthorized servers from occupying device port to ensure connection to GV-ASManager

Modified:

- Requiring users to set a new password upon first-time login
- Password strengths of "Normal" or higher required when changing the password of Administrator account
- Changing the access card number of unknown faces detected by GV-FR2020 from 000-65535 to 000-00000

Firmware V2.21 2019-08-17

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

Fixed:

- Chances of disconnection of GV-GF1921 / 1922 readers and lighting of Purple LED upon card swipe or fingerprint scanning



Firmware V2.20 2019-05-13

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

New:

- Support for GV-CR1320

Modified:

- Ceased support for backing up a copy of log information into micro SD cards once connected to GV-ASManager
- Ability to unlock doors or fire doors from GV-ASManager, without the card, during the Release by Card mode
- Release By Card mode to unlock and lock the door each time a card is presented during the time specified for Release Mode

Firmware V2.15 2018-08-14

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

Fixed

- Occasional failure of the exit button during the Exit Button Schedule
- One snapshot being captured only if swiping cards on more than one GV-FR2020s simultaneously



Firmware V2.12 2018-01-16

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

New:

- GV-AS 21 / 41 / 81 series Controllers to renew the controller data automatically with GV-ASManager after the firmware upgrade

Firmware V2.11 2017-11-09

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

New:

- “Armed status” added to Input Function to enter into arm mode where no cards can be granted access
- “Alarm Keyswitch” added to Output Function to trigger the output after the correct PIN code and Security card are presented

Fixed:

- Some enrolled cards being invalid either
 - after clicking Sync Controller to renew the controller settings on GV-ASManager, or
 - restarting, or powering off and on the controllers
- Missing Door Unlock / Lock messages on the Event Monitor of GV-ASManager after opening or closing the two-person-rule enabled door
- Output not triggered when Output Type is set to Normal and Wiegand is selected, even though the correct card is presented to Wiegand readers



Firmware V2.00 2017-08-15

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110 / 4111
- GV-AS810 / 8110 / 8111

New:

- Number of cards increased from 40,000 to 100,000
- Anti-passback function to monitor the access into a controlled area by users
- Filter option added to Wiegand Configuration to prevent the same card from being swiped multiple times consecutively
- All Zone and Area Occupied added to Output Function to trigger the alarm device when a person enters the controlled area

Changed:

- Latch disabled under Normal Output type not to produce a momentary alarm except triggering Access Granted and Access Denied
- Lock Reset Time changed to 600 seconds in the Parameter Configuration page



Firmware V1.41 2016-12-09

The version history applies to the following models:

- GV-AS210 / 2110 / 2120
- GV-AS410 / 4110
- GV-AS810 / 8110

New:

- Support for GV-FR2020
- Disable local APE option added to “Edit the Card” to exempt the card from the APB setting

Changed:

- Removed support for GV-GF1901 / 1902 / 1911 / 1912 to connect through RS-485
- The alarm event of Forced Open option to be enabled before the Forced open message will be sent

Fixed:

- Failure to release electric locks correctly using the exit button before a card is presented during the Release mode

Firmware V1.40 2016-03-10

New:

- Support for Special Day function in GV-ASManager V4.4.0.0 or later



Firmware V1.30 2015-04-09

New:

- Support for setting device name, rebooting, and restoring default settings through GV-IP Device Utility V8.6.2.0
- Support for passcode function
- Allowing Urgent Code to unlock doors under lockdown mode
- Support for showing input status in the Device View of GV-ASManager
- Support for RS485-B interface on the controller to connect 8 additional readers (GV-AS810 only)

Changed:

- New Web interface
- Removed support for manually entering the card number and pin code to gain access under Card and Pin Code Mode



Firmware V1.23 2014-11-11

New:

- Configurations on Web interface to set connected GV-R1352 / RK1352 to read GID or UID
- Support for allowing specified cards to access doors in Lockdown Mode
- Fast backup and restore function to export and import controller settings
- All Zone Fire Sensor function to trigger the fire sensors on all connected doors when one fire sensor is triggered
- Series Function to extend the All Zone Fire Sensor function to multiple associated controllers

Fixed:

- SSL security issue by supporting TLS V1 only
- Setting for Wiegand E ~ H missing in Output Setting page (GV-AS410 only)
- Incorrect Wiegand settings after GV-AS810 restarts (GV-AS810 only)
- Support for RS485-B interface on the controller to connect 8 additional readers (GV-AS810 only)

Improved:

- Unmount and Check buttons added to Web interface to safely remove inserted SD card and to repair SD card errors
- Current Local Time button added in Time Setting page of Web interface to synchronize controller time with PC time



Firmware V1.22 2014-04-14

New:

- Schedule for exit button to specify when to allow access to the exit button
- Urgent Code function to unlock the associated door when the Urgent Code is entered
- Support for formatting and displaying information of the micro SD card through the controller's Web interface

Fixed:

- Failure to reset APB function for all cards when the Reset Anti-passback function is selected on GV-ASManager
- Inability to unlock the door of GV-GF1901 / 1902 / 1911 / 1912 connected through RS-485 connection if the door direction is set to Out
- Failure to send duress alert during Card and PIN Code Mode when PIN plus 1 is entered on the reader's keypad
- Problem with connecting to GV-ASManager when the log time in micro SD card is before year 2010

Changed:

- Time required for input to trigger output shortened from 1 second to 0.5 seconds
- Support for setting multiple input devices or sensors for the same input function in Web interface



Firmware V1.20 2013-12-09

New:

- Lock Down function for connected doors
- Support for disabling Lock Card Time function for the selected cards
- Support for interlocking a door with multiple doors of the same controller
- Support for typing GeoFinger Server IP address and port in the Extended Reader page to allow remote fingerprint enrollment on all connected GV-GF1921 / 1922 readers

Fixed:

- Door staying unlocked until the specified Lock Reset Time even if the door closes before the end of Lock Reset Time
- Inability to unlock doors 5 – 8 by typing the door password under Card or Common Mode (GV-AS810 only)

Firmware V1.10 2013-05-28

The version history applies to the following firmware version for each device:

- GV-AS210 firmware V1.10
- GV-AS810 firmware V1.10

New:

- Input state setting on Web interface to set input devices to NO or NC circuit
- Support for connecting to GV-CR420 V1.0.1 using MAC address
- LED indicator on GV-CR420 V1.0.1 turning into a solid pink light when network connection is interrupted
- Support for GV-GF1921 / 1922

Fixed:

- Door remains open 1 second longer than the specified lock reset time
- Failure to trigger output device when the reader is using network connection, output type is set to Normal type, and output is set to trigger upon card swipe
- Failure to record output trigger to I/O Log in ASWeb when the output is set to Normal type and trigger upon card swipe