



## GV-Keyboard V3 for GV-System Version History

### Firmware V3.003 2014-10-01

#### Improved:

- Connection speed for switching control among GV-Systems or GV-Control Centers

### Firmware V3.001 2011-07-07

#### Fixed:

- Delay problem of Auto Lock Time
- Problem to smoothly pan and tilt Pelco P / Pelco D (Pelco Spctra 3 SE) PTZ cameras by using GV-Keyboard V3
- Problem to set up the device ID of Pelco P (Pelco Spctra 3 SE) PTZ camera on GV-Keyboard V3
- Problem to control PTZ movement if you press the Previous Camera or Next Camera button during directing the movement by using GV-Joystick, with these PTZ cameras: Pelco P (Pelco Spctra 3 SE), Pelco D (Pelco Spctra 3 SE), Dynacolor (DynaHawk\_Zh701), COP53 (COP 15-CD53W), Dong Yang (Dong Yang DOH-204), Lilin (Lilin 7000NF), COP55 (COP 15-CD55), VIDO (VIDO G65), Samsung (Samsung SCC-641)
- Problem to support up to 256 preset points for Dynacolor (DynaHawk\_Zh701) PTZ camera
- Failure to pan or tilt Dynacolor (DynaHawk\_Zh701) PTZ camera by using GV-Keyboard V3
- Problem to pan and tilt Dynacolor (DynaHawk\_Zh701) PTZ camera in different speed levels by using GV-Joystick
- Issues with horizontal ripples across the screen that occurred when using GV-Keyboard V3 or GV-Joystick to control Pelco P / D (Pelco Spctra 3 SE) PTZ cameras