



Contents

Firmware V1.04 2023-01-12	2
Firmware V1.03 2022-10-25	2
Firmware V1.02 2022-09-02	3
Firmware V1.01 2022-03-29	3



GV-SNVR1612 Version History

Firmware V1.04 2023-01-12

New:

- Support for ONVIF and RTSP connection via DDNS

Fixed:

- Failure of manually adding / deleting / selecting the IP cameras with RTSP URL that contains special characters on the Web interface
- Issue of incorrect Auto Reboot weekday display on the Web interface / SNVR Viewer
- IP camera connection failure and inability to access the live view images on GV-Notify from GV-Cloud Center
- Connection failure when the RTSP URL contains “?”
- Issue of incorrect time display in partial time zones
- Connection failure through RTSP protocol when 3rd party VMS fails to pass the digest authentication
- Audio failure for all channels except for channel 1 when connected to GV-Edge Recording Manager / GV-Control Center

Improved:

- GV-SNVR1612 as an NTP server accessible for connected IP cameras without the external network

Firmware V1.03 2022-10-25

Fixed:

- Failure to connect to UA-R500F2
- Incorrect camera name displayed in the camera list for the following models: UA-R500F2, UA-R560F2, UA-R580F3, and UA-R800F2
- Audio failure when connecting to GV-PBL8800, GV-BX2802, and GV-BX4802
- Failure to connect to a 3rd-party IP camera (IPG-7920PSS-AI)



Firmware V1.02 2022-09-02

Fixed:

- Failure of sending alert from Dispatch Server to the other GV-Center V2 when the original GV-Center V2 is overloaded
- Failure of RTSP connection from third-party XVR
- Failure of displaying GV-FER5702 H.265 streaming
- Failure of restoring to stream 2 once changes are made for multiple division live view after restart

Improved:

- Support for LAN and DHCP server settings through SDK command

Firmware V1.01 2022-03-29

Fixed:

- Failure to display sub stream live view / playback in the multiple-division layout when connected to GV-Edge Recording Manager